



6x50=48 stk



M6x60= 18 stk



Ø6=18 stk




M6=18stk



4x35=24 stk



4x45=10 stk



Sw4=1 stk



6x50=8stk



4x35=4 stk



4x45=10 stk



M6x60= 2 stk



Ø6=2 stk



M6=2 stk

